Spindle Tapes TS-5



Main industry segments


Yarn processing


Applications

Spindle drive

Special features

Abrasion resistant, Antistatic, Constant coefficient of friction, High acceleration, High temperature resistant, Uniform yarn quality, Robustness, High reliability





Product Construction / Design		
Spindle side material	Polyamide (PA)/cellulose (CEL) fabric	
Spindle side surface	Fabric	
Spindle side color	Yellow	
Traction layer (material)	Polyamide (PA) fabric	
Pulley side material	Acrylonitrile-Butadiene-Rubber (NBR)	
Pulley side surface	Sand finish	
Pulley side color	Green	

Product characteristics				
Drive determination	1- / 2- / or 4-spindle ring spinning frames			
Antistatically equipped	Yes			
Adhesive free joining method	No			
Food suitability, FDA conformance	No			
Food suitability, EU conformance	No			

Technical data					
Thickness of belt	0.55	mm	0.02	inch	
Mass of belt (belt weight)	0.50	kg/m²	0.102	lb/sqft	
Tensile force for 1% elongation (k1% after running in) per unit of width (Habasit standard SOP3-013)	1.6	N/mm	9	lbf/in	
Nominal peripheral force per unit of width	5.5	N/mm	31	lbf/in	
Min. operating temperature admissible (continuous)	-20	°C	-4	°F	
Max. operating temperature admissible (continuous)	100	°C	212	°F	
Seamless manufacturing width	1140	mm	44.88	inch	

All data are approximate values under standard climatic conditions: 23°C/73°F, 50% relative humidity (DIN 50005/ISO 554).

Joining related properties

Link to JDS:

Spindle Tapes



Joining method		Thermofix	
		90°	
Pulley diameter (minimum)	mm	15	
	inch	0.59	
Pulley diameter minimum with	mm	15	
counter flection	inch	0.59	

Chemical resistance

Link to 'Chemical resistance information': https://rims.habasit.com

Mode of use or conveyance

Spindle drive

Calculations

With power transmission belts a calculation at least of the belt width and initial elongation is highly recommended. The easiest way is to have belt drives calculated by Habasit representatives.

Recommendation

Observe the indications of the machine handbook from the machine manufacturers

Store spare belts in a cool and dry place and if possible in their original packaging. Protect spare belts from sunlight/UV-radiation/dust/dirt! Check Link for Storage requirements:

"https://tdm.habasit.com/pds/en-us/Storage%20of%20Habasit%20material.pdf"

This product has not been tested according to ATEX standards (atmospheres with explosion risk - ATEX 95 regulation or EU directive 2014/34/EU) and therefore is subject to user's analysis in the respective environment, When changing the direction of rotation (S/Z direction of rotation) the spindle tape can run off the driving pulley

Group Polyamide Spindle Tapes Sub-Group TS Polyamide Spindle Tapes

Item number H010100338

Disclaimer

Product Application Disclaimer (valid for ALL Habasit products and mentioned on all PDS)

This disclaimer is made by and on behalf of Habasit and its affiliated companies, directors, employees, agents and contractors (hereinafter collectively "HABASIT") with respect to the products referred to herein (the "Products"). SAFETY WARNINGS SHOULD BE READ CAREFULLY AND ANY RECOMMENDED SAFETY PRECAUTIONS BE FOLLOWED STRICTLY! Please refer to the Safety Warnings herein, in the Habasit catalogue as well as installation and operating manuals. All indications / information as to the application, use and performance of the Products are recommendations provided with due diligence and care, but no representations or warranties of any kind are made as to their completeness, accuracy or suitability for a particular purpose. The data provided herein are based on laboratory application with small-scale test equipment, running at standard conditions, and do not necessarily match product performance in industrial use. New knowledge and experience may lead to re-assessments and modifications within a short period of time and without prior notice.

EXCEPT AS EXPLICITLY WARRANTED BY HABASIT, WHICH WARRANTIES ARE EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, THE PRODUCTS ARE PROVIDED "AS IS". HABASIT DISCLAIMS ALL OTHER WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, NON-INFRINGEMENT, OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE, ALL OF WHICH ARE HEREBY EXCLUDED TO THE EXTENT ALLOWED BY APPLICABLE LAW. BECAUSE CONDITIONS OF USE IN INDUSTRIAL APPLICATION ARE OUTSIDE OF HABASIT'S CONTROL, HABASIT DOES NOT ASSUME ANY LIABILITY CONCERNING THE SUITABILITY AND PROCESS ABILITY OF THE PRODUCTS, INCLUDING INDICATIONS ON PROCESS RESULTS AND OUTPUT.